

DIRECTOR CHUCK GIPP

November 13, 2017

DAN KOENIGS 4315 VALLEY AVENUE RICEVILLE, IOWA 50466

SUBJECT: Animal Feeding Operation (AFO) Compliance Inspection for:
- Dan Koenigs - Oak Dale Site, County - Howard, Facility #57720

Dear Mr. Koenigs:

Attached is a copy of the report resulting from the Animal Feeding Operation (AFO) facility compliance inspection conducted on November 8, 2017.

Your attention is directed to the recommendations portion of the report.

If you have any questions, or feel this report does not represent the conditions at your facility, please call me at 563/927-2640.

The cooperation and assistance provided by you during the inspection is appreciated.

Sincerely,

Chris Gelner, Environmental Specialist

christopher.gelner@dnr.iowa.gov

1. Olim

Field Services and Compliance Bureau

c: -Stephen Pollard, U.S. EPA Region 7, WWPD/WENF, 11201 Renner Blvd., Lenexa, KS 66219

-Ken Hessenius, FO#3, AFO Enforcement Coordinator, Spencer, IA

enc: -AFO Facility Inspection Report

-MMP Inspection Form

-Animal Feeding Operation (AFO) Regulatory Status Form

-Aerial Photos of Site

Efile: 45 AFO Riceville 57720 Dan Koenigs - Oak Dale Site 110817 Inspection csg

FIELD OFFICE 1, 909 W MAIN ST STE 4, MANCHESTER IA 52057

Phone: 563-927-2640

www.iowadnr.gov

Fax: 563-927-2075

IOWA DEPARTMENT OF NATURAL RESOURCES AFO INSPECTION REPORT

	FACILI	TY DESCRIPT	ION				
FACILITY LOCATION	Facility: Dan Koenigs – Oak Dale Site			Facili	ty ID#: 57720		
	Address: 5535 60th Street	City	: Riceville	State: IA	Zip: 50466		
	PLSS: Section 35, Oak Dale To	wnship (T100N	, R14W), Howard Co				
OWNER	Name: Dan Koenigs		- -	anne en			
	Address:	City:		State: Zip:			
ANIMAL HOUSING TYPE	⊠ Confinement ☐ Open		Combined (Confinement & Open Lot)				
ANIMAL INFORMATION	Animal Type(s)	Capacity	Current Head	Number of Bldgs./Pe			
	Swine - Finish	3,600	3,600	3			
	Date of Construction: 2005		Dates of Expansion	ion: N/A			
	INSPECT	ION INFORMA	TION				
INSPECTION DATE	This Inspection 11/08/2017		Last Inspection: N	WA			
PERSONS INTERVIEWED	Name: Dan Koenigs (available by phone)		Title: Owner				
	Name:	Title:					
NEAREST WATERCOURSE					700000000000000000000000000000000000000		
	Description of Flow Path: South a	about 1,685 ft to	Crane Creek				
	COMPLI	ANCE SUMMA	IDV				
OBSERVATIONS	Nutrient Management: □CNMP □NMP ☑MMP □Other □No formal plan						
	Manure Stockpiling:	Mortality Management:		Runoff from Feed Storage:			
	☐In controlled area☐In compliance with rules☐Not applicable — direct haul☐Stockpiling in an uncontrolled area	⊠Rendering □Composting □Incineration □On-site burial □Landfill		⊠No outdoor feed storage area □Discharge from feedstock storage area is controlled □Feed storage is located in an uncontrolled area			
	Clean Water Diverted: ☐Yes ☑No	Discharge to a via Manmade ☐Yes	a Water of the U.S. Conveyance: ⊠No	Direct Animal Contact with Waters of the U.S.: ☐Yes ☑No			
	Adjacent Facilities (by same owner/operator): Confinement Open Lot None Evidence of Discharges: Yes No						
NPDES PERMIT STATUS COMPLIANCE STATUS	The facility, as observed during the permit. NPDES permit is required: This facility appeared to be in compine permit. Actual conditions may the permit in t	Yes _⊠No pliance with lowa	a's environmental red	gulations at the	lime of the		
	Facility is in compliance: ⊠Yes	□No	ar the operation and	mainterfallee 01	ule lacility.		
UTHENTICATION	Inspector: Oh Gen	Date:///2//-7	Reviewer: 1800	riguison Da	ite:///13/17		

IOWA DEPARTMENT OF NATURAL RESOURCES AFO INSPECTION REPORT

FACILITY EVALUATION

Facility

This facility consists of (3) confinement buildings housing a capacity of 3,600 finish swine. Manure is stored in below-building pits. Manure structures were observed during the inspection and no discharge was noted. Mortalities are disposed of by rendering. Mr. Dan Koenigs was available by telephone during the inspection.

Manure Management Plan (MMP)

The MMP and manure application records were reviewed during the inspection. No deficiencies were noted.

Bulk Bins

During the facility inspection, it was noted that feed was contained in a bulk bin feed system. The bins, feed tubes and various attachments appeared to be intact and effectively containing feed. I did not observe feed spilled on the ground from feed transfer to the bins. This part of the operation should be inspected frequently as runoff water could carry spilled feed into a water of the state where it could create violations of state water quality standards. Discharge of such pollutants would potentially require a National Pollutant Discharge Elimination System (NPDES) permit.

Rendering

Dead animals are disposed of by rendering at this site. The staging area for mortality rendering pick-up was observed. This staging area appears to be a good location to prevent runoff to a water of the state or man-made conduit like a ditch, tile line or culvert that leads to a water of the state. This part of the operation should be inspected frequently as runoff water could carry leachate into a water of the state where it could create violations of state water quality standards. Discharge of such pollutants would potentially require a National Pollutant Discharge Elimination System (NPDES) permit.

Bio-Security

Prior to the inspection, bio-security was discussed with Mr. Koenigs and it was agreed upon that DNR bio-security SOP would be followed. DNR bio-security SOP was followed during the inspection.

RECOMMENDATION

Regularly walk around the facility to monitor for discharges and needed repairs.

SUMMARY

- The facility, as observed, was considered a Large CAFO based on the capacity of animals at the animal feeding operation.
- No discharge was observed during the inspection and no evidence of past discharge was observed.
 No NPDES permit is required at this time.

IOWA DEPARTMENT OF NATURAL RESOURCES ENVIRONMENTAL SERVICES DIVISION



Field Office #1 909 W Main Ste 4

Field Office #2 2300 15th St SW

Field Office #3 1900 N Grand Ave

Field Office #4 1401 Sunnyside Ln

Field Office #5 7900 Hickman Rd Ste 200

Field Office #6 1023 W Madison

Curre Last:		Manure Managemer Number of Animals: 3,600	Animal Units: 1,440	N-based⊠ P-based □	Facility Location County: Howard	Fa	cility ID: 577	
Pre-	llity Tier Status visit: -visit:	1 2 3 Violation(s) Comments					management and the second
	ical Violation(s) nnical Violation(s)]					Ministration	
Faci Add	lity Owner Informati ress of Facility: 55	oenigs – Oak Dale Site Pe on & Address Unchanged 335 60 th Street, Riceville, Io ny other animal feeding op	? Yes ⊠ No □ (Dat owa 50466			641/98	5-2138	Material de la
	P Contents		eing met for the follow	AND DESCRIPTION OF THE PARTY OF		Vaa	TNA	51.0
a.	Calculations to det	ermine land area for applica		ing rems:		Yes	No	N.A.
b.		phosphorus available, credi		55.17(5)]?				1 ===
c.	Optimum crop yiel	d, crop usage rate, and soils	maps [65.17(6)]?					+ H
d.	Manure application	n methods and timing of app	plication [65.17(7)]?	***************************************			十一	十一一
e.		e application and landowner					十一	十一
f.	Estimate of annual	animal production and amo	ount of manure produc	ed [65.17(9)]?			1 1	十一
g.	Methods, structure	es, or practices to reduce soi	il loss and potential sur	face water pollut	ion (conservation	Name of the last o		1 -
		dible land) [65.17(10)]?				\boxtimes		
<u>h.</u>	Does P Index no. ge	enerated correspond with P	Index no. in plan? [65.	17(17)]				
i.		pling methods being used t		PAGE CONTROL OF THE PAGE OF TH				
	rds Review		ng met for the followin	g items?		Yes	No	N.A.
<u>j.</u>		t MMP [65.17(12)]?						
<u>k.</u>	Records Kept for 5	years (or crop rotation if lo	onger) maintained [65.1	L7(13)]?				
<u>l.</u>	Methods of applica					\boxtimes		
m. n.		e was applied [65.17(13)b]?						
0.	Manure application	application and number of	acres [65.17(13)c]?				<u> </u>	
<u>р.</u>		t for fields not owned or ren	+					14
		ure Storage/Handling/Appl				<u> </u>		
	mal Disposal		ication ing met for the followin	a Hamai				
q.		uctures appear to be proper	rly operated & maintain	ng itellist nod 165 28.65 1.51	3	Yes	No	N.A.
r.	Dead animals dispo	sed of properly [567 IAC 100	0.4(455B) & Code of Io	wa 167 1812				+
	Type: Compost		Burial Render					1 -
)iscu:	ssion Items:	Were the following it				Yes	No	N.A.
s.	Manure release not	ification made within 6 hou				Ø	П	1117
t.	Deficiencies, violation	ons, and tier status?				Image: Simple state of the control of	一一	1
u.		improvements, environmer					一一	H
V.,		s certified [65.19]? Applicate	or name/number:				Ħ	一
W.	Proper manure appl	ication [65.3(2)-(3)]?						同一
omn	nents Manure app	lication is conducted d	uring the fall by Ag	Liquid, LLC – C	MS 1262			Account of the last of the las
~~************************************						Similar pales o se el constitue con constitue con constitue con	TOTAL CONTRACTOR CONTR	- The state of the



Animal Feeding Operation (AFO) Regulatory Status

Facility Name:	Dan Koenigs – Oak Dale Site	Facility ID:	57720	County: Howard
	Large CAFO — Discharging Large CAFO — No discharg Large CAFO — Has NPDES Medium CAFO — NPDES Pomedium AFO — No NPDES Medium AFO — Has NPDES Designated CAFO — NPDES Small AFO — No NPDES Pe	e – No NPDES Per Permit ermit Required Required S Permit S Permit Required	equired mit Required	
Please note that	on was made based on conditions and the regulatory status of the facility ca ed during the inspection.	l observations mad n change if condit	de at the time of the facil	of the inspection on 11/08/2017. ity change or are different from
Inspector:	Vii Gelm		Date:	11/8/17

Regulatory Definitions of Large CAFOs, Medium CAFOs, and Small CAFOs

These regulatory definitions are from the Code of Federal Regulations (CFR), implementing the federal Clean Water Act.

A Large CAFO confines at least the number of animals described in the table below.

A Medium CAFO falls within the size range in the table below and either:

- "(A) Pollutants are discharged into waters of the United States through a man-made ditch, flushing system, or other similar man-made device; or
- (B) Pollutants are discharged directly into waters of the United States which originate outside of and pass over, across, or through the facility or otherwise come into direct contact with the animals confined in the operation." 40 CFR 122.23(b)(6)(ii)

If an operation is found to be a significant contributor of pollutants to waters of the United States, the permitting authority may designate a medium-sized facility as a CAFO as provided in 40 CFR 122.23(c).

A Small CAFO confines the number of animals listed in the table and has been designated as a CAFO by the permitting authority after determining that it is a significant contributor of pollutants to waters of the United States as provided in 40 CFR 122.23(c).

Animal Sector	Size Thresholds (number of animals)				
	Large CAFOs	Medium CAFOs	Small CAFOs		
cattle or cow/calf pairs	1,000 or more	300 - 999	less than 300		
mature dairy cattle	700 or more	200 - 699	less than 200		
veal calves	1,000 or more	300 – 999	less than 300		
swine (weighing over 55 pounds)	2,500 or more	750 -2,499	less than 750		
swine (weighing less than 55 pounds)	10,000 or more	3,000 - 9,999	less than 3,000		
horses	500 or more	150 - 499	less than 150		
sheep or lambs	10,000 or more	3,000 - 9,999	less than 3,000		
turkeys	55,000 or more	16,500 - 54,999	less than 16,500		
chickens other than laying hens (other than a liquid manure handling system)	125,000 or more	37,500 – 124,999	less than 37,500		
laying hens (other than a liquid manure handling system)	82,000 or more	25,000 - 81,999	less than 25,000		

Dan Koenigs – Oak Dale Site 5535 60th Street Riceville, Iowa 50466 Facility ID# 57720



